

AD-A105 307

HOSKINS-WESTERN-SONDEREGGER INC LINCOLN NE

F/G 13/13

NATIONAL DAM SAFETY PROGRAM, RISS LAKE DAM (MO 20128), MISSOURI--ETC(U)

SEP 78 H P HOSKINS

DACW43-70-C-0155

NL

UNCLASSIFIED

1 of 1
40 A
10-50

END
DATE
FILMED
11-81
DTIC

MISSOURI **LEVEL** ¹¹ _{PS} (1)
MISSOURI-KANSAS CITY BASIN

RISS LAKE DAM

JACKSON COUNTY, MISSOURI

MO 20128

AD A105307

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

DTIC FILE COPY



DTIC
ELECTE
S OCT 9 1981 D
D

PREPARED BY: HOSKINS-WESTERN-SONDEREGGER, INC.

FOR: STATE OF MISSOURI

SEPTEMBER, 1978

81 10 7 104

DISTRIBUTION STATEMENT A

Approved for public release.
Distribution Unlimited

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A105	307
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Riss Lake Dam (MO 20128) Jackson County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) HOSKINS-WESTERN-SONDEREGGER, INC.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-70-C-0155
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) National Dam Safety Program. Riss Lake Dam (MO 20128), Missouri - Kansas City Basin, Jackson County, Missouri. Phase I Inspection Report.		12. REPORT DATE 11 September 1978
16. DISTRIBUTION STATEMENT Approved for release; distribution unlimited.		13. NUMBER OF PAGES Approximately 40
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		15. SECURITY CLASS. (of this report) UNCLASSIFIED
18. SUPPLEMENTARY NOTES		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

DD FORM 1 JAN 73 1473

EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

374131

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 NORTH 12TH STREET
ST. LOUIS, MISSOURI 63101

IN REPLY REFER TO

SUBJECT: Riss Lake Dam Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Riss Lake Dam:

It was prepared under the National Program of Inspection of Non-Federal Dams

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- 1) Spillway will not pass 50 percent of the Probable Maximum Flood
- 2) Overtopping could result in dam failure.
- 3) Dam failure significantly increases the hazard to loss of life downstream

SUBMITTED BY: _____

Chief, Engineering Division

SIGNED

28 FEB 1976

Date

APPROVED BY: _____

Colonel, CE, District Engineer

SIGNED

26 FEB 1979

Date

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

DTIC
ELECTE
OCT 9 1981
S D

PHASE I REPORT

NATIONAL DAM SAFETY PROGRAM

Name of Dam	Riss Lake Dam
State Located	Missouri
County Located	Jackson County
Stream	Tributary to Round Grove Creek
Date of Inspection	September 21, 1978

Riss Lake Dam was inspected by an interdisciplinary team of engineers ~~from Hoskins-Western-Sonderregger, Inc.~~ The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers, and developed with the help of several Federal and State agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as an intermediate-size dam with a high downstream hazard potential. Failure would threaten life and property. The estimated damage zone extends three miles downstream of the dam. Within the damage zone are three to four houses and associated buildings, one railroad crossing, and four improved road crossings.

Our inspection and evaluation indicates that the spillway does not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. The spillway will not pass a 100-year flood (flood having a one percent chance of being exceeded in any year). The spillway will pass 12% of the Probable Maximum Flood without overtopping the dam. The Probable Maximum Flood (PMF) is defined as the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.

Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These analyses should be obtained in the future.

Deficiencies visually observed by the inspection team were dense growth of trees, bushes, and weeds growing on the crest as well as both slopes, numerous erosion pockets in the downstream slope, low spots in the crest of the dam where water ponds, severe erosion of the spillway channel, and the channel downstream from the eroded spillway is clogged with trees and brush.

Several items of preventive maintenance need to be initiated by the owner. These are described in detail in the body of the report.

H. P. Hoskins

Harold P. Hoskins, P.E.
Hoskins-Western-Sonderregger, Inc.
Lincoln, Nebraska




PHOTO NO. 1
OVERVIEW LOOKING WEST TO DAM

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

RISS LAKE DAM
ID NO. MO 20128

TABLE OF CONTENTS

<u>Paragraph No.</u>	<u>Title</u>	<u>Page No.</u>
SECTION 1 - PROJECT INFORMATION		
1.1	General	1
1.2	Description of Project	1
1.3	Pertinent Data	2
SECTION 2 - ENGINEERING DATA		
2.1	Design	5
2.2	Construction	5
2.3	Operation	5
2.4	Evaluation	5
SECTION 3 - VISUAL INSPECTION		
3.1	Findings	6
3.2	Evaluation	7
SECTION 4 - OPERATIONAL PROCEDURES		
4.1	Procedures	8
4.2	Maintenance of Dam	8
4.3	Maintenance of Operating Facilities	8
4.4	Description of Any Warning System in Effect	8
4.5	Evaluation	8
SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	9
SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	11
SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1	Dam Assessment	12
7.2	Remedial Measures	12

APPENDIX A - MAPS

Plate 1
Plate 2

Vicinity Topography
Location Map

APPENDIX B - PHOTOGRAPHS

Photographs of Dam and Lake (No. 2 through No. 12)

APPENDIX C - PLAN, SECTION AND PROFILE

Phase I

Plan, Profiles and
Cross Section

APPENDIX D - HYDROLOGIC COMPUTATIONS

Sheets 1, 2 and 3 of 10
Sheet 4 and 5 of 10
Sheet 6 of 10
Sheet 7 of 10
Sheet 8 of 10
Sheet 9 of 10
Sheet 10 of 10

Computer Input (PMF, 0.5PMF, 100 Year)
Computer Output (PMF)
Computer Output (0.5PMF)
Computer Output (100 Year)
Spillway Rating Curve
Dam Rating Curve
Combined Outfall Rating Comp.

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. Authority. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of Riss Lake Dam be made.
- b. Purpose of Inspection. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.
- c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many State agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances.
 - (1) This dam is an earth embankment about 800 feet in length and 42 feet in height. Topography around the dam is moderately steep. Materials on the slopes consist of loess or reworked loess soils underlain by shales and limestones.
 - (2) The spillway consists of a channel at the left abutment. Headcut erosion caused a partial breach in 1977. An embankment plug was subsequently constructed in the eroded spillway with a broomed concrete invert to carry low flows.
 - (3) An 8-inch drawdown siphon penetrates the embankment near the normal pool level at center line station 2+80.
 - (4) Pertinent physical data are given in Paragraph 1.3 below.
- b. Location. The dam is located in the west central portion of Jackson County, Missouri, as shown on Plate 2. The dam and the lake formed by the dam are shown on Plate 1 in the NW $\frac{1}{4}$ of Section 28, T49N, R32W.

- c. Size Classification. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c, above. Based on these criteria, this dam and impoundment are in the intermediate-size category.
- d. Hazard Classification. Guidelines for determining hazard classification are presented in the same guidelines as referenced in paragraph c, above. Based on referenced guidelines, this dam is in the High-Hazard Classification. The estimated damage zone extends three miles downstream from the dam. Within this zone are three to four houses and associated buildings, one railroad crossing and four improved road crossings.
- e. Ownership. This dam is owned by BMA Properties, Inc., BMA Tower, Kansas City, Missouri 64141. Attention: Kent F. Turner.
- f. Purpose of Dam. The dam forms a 21-acre \pm recreational lake.
- g. Design and Construction History. No design or construction data were available. The dam was constructed in the early 1930's by the W.P.A. The impoundment covers a former limestone quarry.
- h. Normal Operating Procedure. There are no established procedures for operating the drawdown siphon. No information was available on the fluctuation of the lake level. It was reported that flow passed over the top of the dam for several hours in 1977. This overtopping resulted from a rain reportedly of more than 12 inches in the area.

1.3 PERTINENT DATA

- a. Drainage Area - 292 acres (0.457 square miles).
- b. Discharge at Damsite.
 - (1) All discharge at damsite is through an uncontrolled spillway with earth channel and poured concrete floor.
 - (2) Estimated maximum flood at damsite-discharge unknown but probably occurred in 1977.
 - (3) The spillway capacity varies from 0 c.f.s. at spillway crest (930.0 feet) to 156 c.f.s. at low point of dam crest (931.9 feet).
 - (4) There is no emergency spillway.
- c. Elevations (Feet above M.S.L.).
 - (1) Top of Dam (low point) - 931.9

- (2) Spillway crest - 930.0
- (3) Streambed at center line of dam - 890.0±.
- (4) Maximum tailwater - unknown.
- d. Reservoir. Length of maximum pool (Top of Dam) - 1900 feet±.
- e. Storage (Acre-feet).
 - Top of dam (low point) - 190
 - Spillway crest - 150
- f. Reservoir Surface (Acres).
 - (1) Top of dam (low point) - 23±
 - (2) Spillway crest - 21±.
- g. Dam.
 - (1) Type - earth embankment
 - (2) Length - 800 feet±
 - (3) Height - 42 feet±
 - (4) Top width - 18 feet to 24 feet
 - (5) Side slopes
 - (a) Downstream - 3.0 to 4.4H on 1V - average 3.5H on 1V (measured with hand level)
 - (b) Upstream - exposed slope - 3H on 1V
 - (6) Zoning - unknown
 - (7) Impervious core - unknown
 - (8) Cutoff - unknown
 - (9) Grout curtain - unknown
 - (10) Riprap - the upstream face is plated with hand-placed limestone rock, generally less than 12 inches in maximum dimension.
- h. Diversion and/or Regulation. None

i. Spillway

(1) Principal

- (a) Type - Earth and rock channel with spillway floor of rough poured concrete smoothed by hand rake.
- (b) Central section - Approximate bottom width of 20 feet and varying side slopes averaging about 9:1.
- (c) Crest elevation - 930.0 feet m.s.l.
- (d) Upstream channel - None
- (e) Downstream channel - Filled with fallen trees and brush and badly eroded.

(2) Emergency - None

j. Regulating Outlet - Eight-inch pipe siphon with gate valve. Motor operated with intake approximately 20 feet below water surface. Used only to lower lake in case of emergency.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

No design data were available for this dam.

2.2 CONSTRUCTION

No construction data were available, although it was reported that the dam was built in the 1930's by the W.P.A.

2.3 OPERATION

An eight-inch siphon has been installed near station 2+80 as a draw-down works. It was reported that the siphon could lower the lake as much as one foot per day, when in operation, and that the siphon inlet was about 20 feet below the permanent pool level. There were no other controlled discharge structures for this dam.

2.4 EVALUATION

- a. Availability. There were no engineering data available for this dam.
- b. Seepage and stability analyses. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading condition and made a matter of record.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

- a. General. A visual inspection of Riss Lake Dam was made on September 21, 1978. Engineers from the firm of Hoskin-Western-Sonderegger, Inc., making the inspection were: Stephen Nickel, Geology and Soil Mechanics, Gordon Jamison, Hydrology and Hydraulics, Garold Ulmer, Civil Engineer, and Richard Walker, Hydrology. Specific observations are discussed below.
- b. Dam. The upstream slope has a covering of hand-placed riprap, through which weeds, bushes, and trees up to 10 inches in diameter are growing. Neither slides nor serious erosion were noted in the upstream slope. The crest and the downstream slope were also covered with a dense growth of trees, bushes, weeds, and grass. No seeps or slides were noted on the downstream slope, although there were numerous small depressions up to 2 feet in diameter and up to 1 foot deep. These holes appeared to be erosion pockets which could have developed during overtopping of the dam in 1977. The soils exposed on the surface of the dam were found to be silty clay (CL) and clay (CH). The dense growth of trees, bushes, weeds, and grasses on the upstream and downstream slopes of the dam and on the crest made evaluation of surface conditions extremely difficult.

The abutments are mantled with silty clay (CL) soils which overlie shales and limestones. It was reported that the reservoir area was originally a limestone quarry and that the center and north portions of the embankment sit above a nearly vertical limestone cut face. However, no seepage was noted in the abutments, on the downstream slope, or at the downstream toe. Some low areas were found on the crest where water had ponded and where cracks were evident. The cracks were parallel to the axis of the dam but were not over 5 or 10 feet long. They appeared to be shrinkage cracks.

- c. Appurtenant Structures. The spillway consists of an earth channel, with a broomed concrete invert, that drops sharply down the left abutment. The spillway channel follows the route of the original spillway channel, but the flowline has eroded up to 20 feet vertically at some locations. The original limestone masonry walls of the spillway channel remain, generally intact, high above the existing flowline. It was reported that head-cutting erosion of the spillway channel began shortly after construction and reached the dam during high flows in 1977. At that time, erosion of the channel lowered the lake level about 7 feet. The spillway was then repaired in order to bring the lake back to its normal level. A plug of compacted soil was constructed in the eroded spillway channel. The plug is about 100

feet long, gently sloping on top, and steeply sloping on the downstream side. The concrete spillway invert is constructed on this earth plug and stops when it reaches the eroded spillway channel. At station 2+80 there is an 8-inch steel siphon that has been installed as a drawdown works. The intake is reported to be about 20 feet below the normal pool level. Where the siphon passes through the embankment, its top is at the normal pool level. After emerging from the embankment, the pipe rests on the downstream slope with an unprotected discharge about 30 feet below the downstream toe. The siphon was carrying no flow at the time of the inspection. The uncontrolled spillway and the drawdown siphon are the only structures to control pool levels at this dam.

- d. Reservoir Area. No wave wash, excessive erosion, or slides were observed along the shore of the reservoir.
- e. Downstream Channel. The channel below the eroded spillway is poorly defined and is clogged with trees and brush. About 1000 feet downstream from the dam the channel crosses under a paved road. The exact location of the channel in the trees could not be determined from the road.
- f. Downstream Hazards. The downstream hazards are described in Section 5.

3.2 EVALUATION

The trees on the upstream and downstream slopes of the dam and on the crest, if left uncontrolled, have the potential of causing failure of the dam by piping along the roots. The crest requires regrading to prevent the ponding of water. The spillway requires immediate attention. Any large spillway flow could wash out the plug embankment.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

No regulating procedures exist for the operation of the drawdown siphon. It was reported that water flowed over the top of the dam in 1977.

4.2 MAINTENANCE OF DAM

The growth of trees, bushes, and weeds on the embankment and the severe erosion of the original spillway indicate the lack of regular maintenance.

4.3 MAINTENANCE OF OPERATING FACILITIES

The drawdown siphon was recently installed and shows no lack of maintenance.

4.4 DESCRIPTION OF WARNING SYSTEM IN EFFECT

The inspection team is not aware of any warning system at this dam.

4.5 EVALUATION

Trees and brush growing on the embankment could lead to the potential of failure if not controlled.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. Design Data. No design data were found for this dam.
- b. Experience. The drainage area, reservoir surface area, and elevation-storage data were developed from the U.S.G.S. Independence, Missouri (7.5 minute) Quadrangle topographic map. The hydraulic computations for the spillway and dam overtopping discharge ratings were based on information obtained from field measurements made during the field inspection.
- c. Visual Observations.
 - (1) It would appear that the spillway floor would be subject to severe erosion in case of a major flood.
 - (2) Spillway exit channel conditions could cause considerable scour to downstream side of dam.
 - (3) The spillway is part of the left abutment of the dam and high flows in the spillway could cause problems to the dam.
 - (4) The heavy growth of trees on both the upstream and downstream faces could also cause severe problems.
- d. Overtopping Potential. The spillway is too small to pass the one-half Probable Maximum Flood or the 100-year flood without overtopping. The spillway will pass 12% of the Probable Maximum Flood without overtopping. The results of the routings through the reservoir are tabulated in regards to the following conditions.

<u>Frequency</u>	<u>Peak Inflow Discharge c.f.s.</u>	<u>Peak Outflow Discharge c.f.s.</u>	<u>Maximum Pool Elevation</u>	<u>Freeboard Top of Dam Min. Elev. 931.9</u>	<u>Time Dam Overtopping Hrs.</u>
100-Yr.	640	550	932.6	-0.7	3.5
1/2 PMF	1440	1370	933.2	-1.3	6.2
PMF	2880	2810	933.9	-2.0	10.2
0.12 PMF	330	160	931.9	0	--

According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, this dam is classified as having a high hazard rating and an intermediate size. Therefore, the PMF is the test for the adequacy of the dam and its spillways.

The St. Louis District, Corps of Engineers, in a letter dated 11 August, 1978, has estimated the damage zone as extending three miles downstream from the dam. Within the damage zone are three to four houses and associated buildings, one railroad crossing, and four improved road crossings.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

- a. Visual Observations. Visual observations of items which adversely affect the stability of the dam are discussed in Section 3. These include the following features: brush and trees on the embankment faces and crest, low areas on the crest which permit water to pond, and the erosion-damaged spillway which has been repaired in what must be considered a temporary manner.
- b. Design and Construction Data. No design or construction data were available.
- c. Operating Records. The only structure capable of being operated is the drawdown siphon. No operating records exist for this structure.
- d. Post-Construction Changes. The drawdown siphon has been constructed recently. It penetrates the dam just below the normal pool elevation at center line station 2+80. No seepage was noted where the siphon emerges onto the downstream slope. The siphon should pose no hazard to the stability of the dam. The deteriorated condition of the spillway and the repairs that have been performed constitute a hazard to the integrity of the embankment.
- e. Seismic Stability. This dam is in Seismic Zone 1. An earthquake of the magnitude used for design in this zone is not expected to cause structural failure of this dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. Safety. Several items were noted during the visual inspection which could seriously threaten the safety of the dam if not controlled. These items include uncontrolled vegetation on the slopes and crest of the dam, the presence of low areas on the crest where water can pond, and the deteriorated condition of the spillway. The Probable Maximum Flood will overtop the dam. The spillway will pass 12% of the PMF before the dam is overtopped.

Overtopping of this dam in 1977 had no reported major effect downstream.

- b. Adequacy of Information. Since no engineering or construction data were available, the conclusions of this report are based upon performance history and visual observations. The inspection team considers that these data are sufficient to support the conclusions herein. Neither a seepage nor a stability analysis was found. This is a deficiency which should be corrected in the near future. Additional studies would be required to assess downstream hazards due to overtopping and/or breaching of this dam.
- c. Urgency. The remedial measures recommended in paragraph 7.2 should be accomplished as soon as possible.
- d. Necessity for Phase II. A Phase II investigation is not called for. However, additional engineering data and analyses should be obtained by the owner, at the owner's expense, to evaluate and design recommended remedial measures.
- e. Seismic Stability. The dam is located in Seismic Zone 1. An earthquake of the magnitude used for design in this seismic zone is not expected to be hazardous to this dam.


7.2 REMEDIAL MEASURES

- a. Alternatives. If breaching of this dam due to overtopping will endanger life or property downstream, the size of the spillway and/or the height of the dam should be increased and/or the permanent pool elevation should be lowered so that the Probable Maximum Flood can be passed without overtopping the dam. Regardless of which of these alternatives is chosen, additional investigations and analyses should be conducted to determine the structural characteristics and stability of the present embankment. These investigations should include a determination of

whether high seepage pressures exist beneath the embankment or the downstream toe and the application of these findings in the stability analysis. The services of an engineer experienced in the design of dams should be obtained to perform the investigations and analyses of the present dam and to design the appropriate modifications and remedial measures.

- b. O & M Maintenance and Procedures. The following O & M maintenance and procedures are recommended.
- (1) A program should be developed and put into action to remove trees and brush from the dam and to control other vegetation.
 - (2) The crest should be regraded to permit proper surface drainage.
 - (3) The spillway should be restored in such a manner that erosion will no longer threaten the embankment or the spillway itself. This work should be planned in conjunction with the consideration of the alternatives in paragraph a., above.
 - (4) The dam should be inspected regularly by qualified personnel to determine the presence of seepage on the downstream slope, in the abutments, below the downstream toe, or in the spillway channel, to determine the presence of slides in the downstream slope, and to observe the upstream slope for any erosional damage.

APPENDIX A
MAPS



APPENDIX B
PHOTOGRAPHS



PHOTO NO. 2
UPSTREAM SLOPE
FROM SPILLWAY
INLET



PHOTO NO. 3
UPSTREAM SLOPE
FROM RIGHT
ABUTMENT




PHOTO NO. 4
LOOKING NORTH
FROM CENTER LINE
STATION 2+00



PHOTO NO. 5
LOW AREA ON CREST
CENTER LINE STATION
1+95. NOTE
PENCIL POINTING
TO CRACK AT BOT-
TOM OF PHOTO




PHOTO NO. 6
SIPHON ENTERING
EMBANKMENT AT
CENTER LINE STA-
TION 2+80




PHOTO NO. 7
SIPHON ON
DOWNSTREAM
SLOPE




PHOTO NO. 8
SIPHON OUTLET
WITH NO FLOW



PHOTO NO. 9
LOOKING UPSTREAM
IN SPILLWAY



PHOTO NO. 10
LOOKING DOWN-
STREAM IN
SPILLWAY




PHOTO NO. 11
LOOKING UPSTREAM
AT DOWNSTREAM
SLOPE OF DAM




PHOTO NO. 12
LOOKING UPSTREAM
IN EXIT CHANNEL
1000 FEET BELOW
DAM



APPENDIX C
PLAN, SECTION AND PROFILE



PROFILE OF DAM



CROSS SECTION
AT STA. 3+00



RISS LAKE DAM
NATIONAL DAM SAFETY PROGRAM
PHASE I

Rough Poured
Concrete Smoothed
by Hand Bake

APPENDIX D
HYDROLOGIC COMPUTATIONS

HYDROLOGIC COMPUTATIONS

1. The Mockes dimensionless standard curvilinear unit hydrograph and the SCS TR-20 program were used to develop the inflow hydrographs (see Plate D1). The inflow hydrograph for the 100-year flood was generated by the consultant using the TR-20 program.
 - a. Six-hour, twelve-hour, and twenty-four-hour 100-year rainfall for the dam location was taken from NOAA Technical Paper 40. The 24-hour probable maximum precipitation was taken from the curves of Hydrometeorological Report No. 33 and current Corps of Engineers and St. Louis District policy and guidance for hydraulics and hydrology.
 - b. Drainage area = 0.457 square mile (292 acres).
 - c. Time of concentration of runoff = 25 minutes.
 - d. The antecedent storm conditions were heavy rainfall and low temperatures which occurred on the previous 5 days (SCS AMC III). The initial pool elevation was assumed at the crest of the emergency spillway.
 - e. The total 24-hour storm duration losses for the 100-year storm were 1.27 inches. The total losses for the 24-hour duration 1/2 PMF storm were 1.39 inches. The total losses for the PMF storm were 1.62 inches. These data are based on soils B group, woods and urbanized cover weighted to produce SCS input runoff curve No. 85 from SCS AMC II converted by TR-20 to curve No. 94 SCS AMC III.
 - f. Average soil loss rates = 0.05 inch per hour approximately.
2. The emergency spillway discharge rating was developed using the Corps of Engineers Surface Water Profile HEC-2 computer program. The flow over the dam crest was computed by two methods due to effect of the numerous trees on the upstream face of the dam near the upstream crest. Flows were first computed using the broad-crested weir equation $Q = CLH^{1.5}$ with the effective Length reduced due to the trees by application of the contraction formula $L = L' - 2(NK_0 + K_2)H_e$ as found in USBR publication Design of Small Dams. The Corps of Engineers HEC-2 computer program was also used so that values of "n" could be applied. The HEC-2 program gave higher heads for the same discharge, indicating more head-loss effect due to the trees. A copy of the spillway, top-of-dam, and combined rating curves are attached. The HEC-2 rating was therefore used for the dam overtopping.
3. Floods were routed through the reservoir using the TR-20 program to determine the capabilities of the spillways and dam embankment crest.

The unit hydrograph computation duration interval is computed as $0.17 T_c$ by the TR-20 program. The input-output data for the TR-20 program used to develop the hydrographs for the PMF, 0.5 PMF, and 100-year flood are attached. The storm rainfall patterns, inflow hydrographs and routed outflow hydrographs are shown on Plate D1.




PLATE D

HYDROLOGY PROGRAM FOR IBM 1130 - DATED JULY, 1968

EXECUTIVE CONTROL CARD

NO DAM INSP-RISS LAKE DAM

C TABLE VFLOCITY INCREMENT = 0.200

0	0.0000	0.0000	0.1000	0.2500	0.3200
0	0.3700	0.0400	0.4500	0.4000	0.5100
0	0.4400	0.5700	0.5300	0.6100	0.6300
0	0.4500	0.6600	0.7100	0.6900	0.7900
0	0.7600	0.7700	0.7700	0.7400	0.7500
0	0.7900	0.8000	0.8100	0.8100	0.8200
0	0.8200	0.8300	0.8300	0.8400	0.8400
0	0.8600	0.8500	0.8500	0.8600	0.8600
0	0.8600	0.8600	0.8700	0.8700	0.8700
0	0.8900	0.8800	0.8900	0.8900	0.8900
0	0.9000	0.9000	0.8900	0.9000	0.9000
0	0.9100	0.9100	0.9000	0.9100	0.9100
0	0.9200	0.9200	0.9100	0.9200	0.9200
0	0.9200	0.9200	0.9200	0.9300	0.9300

9 ENDTBL

STRUCTURE NO. 1

ELEVATION	DISCHARGE	STORAGE
930.0001	0.0000	150.0000

9 ENDTBL

DIMENSIONLESS HYDROGRAPH - DELTA T = 434.00

0	0.0000	0.0300	0.1000	0.1900	0.3100
0	0.4700	0.6600	0.8200	0.9300	0.9900
0	1.0000	0.9900	0.9300	0.8600	0.7800
0	0.6000	0.5600	0.4600	0.3900	0.3300
0	0.2000	0.2400	0.2070	0.1740	0.1470
0	0.1200	0.1070	0.0910	0.0770	0.0660
0	0.0550	0.0470	0.0400	0.0340	0.0290
0	0.0250	0.0210	0.0180	0.0150	0.0130
0	0.0110	0.0090	0.0080	0.0070	0.0060
0	0.0030	0.0020	0.0030	0.0020	0.0010
0	0.0000	0.0000	0.0000	0.0000	0.0000

9 ENDTBL

RAINFALL TABLE NO. 1 TIME INCREMENT = 0.50

0	0.0000	0.0080	0.0170	0.0260	0.0350
0	0.0450	0.0550	0.0650	0.0760	0.0870
0	0.0990	0.1120	0.1250	0.1400	0.1560
0	0.1740	0.1940	0.2190	0.2440	0.3030
0	0.5150	0.5030	0.6240	0.6540	0.6620
0	0.7050	0.7270	0.7480	0.7670	0.7840
0	0.8000	0.8160	0.8300	0.8440	0.8570
0	0.8700	0.8820	0.8910	0.9050	0.9160
0	0.9200	0.9360	0.9460	0.9560	0.9650
0	0.9740	0.9830	0.9920	1.0000	1.0000

9 ENDTBL

RAINFALL TABLE NO. 2 TIME INCREMENT = 0.02

0	0.0000	0.0100	0.0200	0.0200	0.0300
0	0.0400	0.0500	0.0600	0.0700	0.0800
0	0.1000	0.1100	0.1300	0.1400	0.1700
0	0.1900	0.2200	0.2700	0.3500	0.4400
0	0.5200	0.6000	0.6300	0.6600	0.6800
0	0.7000	0.7200	0.7400	0.7600	0.7700
0	0.7900	0.8000	0.8200	0.8300	0.8400
0	0.8500	0.8700	0.8800	0.8900	0.9000
0	0.9100	0.9200	0.9300	0.9400	0.9500
0	0.9670	0.9633	0.9700	0.9800	0.9900
0	1.0000	1.0000	1.0000	1.0000	1.0000

9 ENDTBL

RAINFALL TABLE NO. 3 TIME INCREMENT = 0.50

21.00 DISCHG 103.282 / 98.82 931.23 90.49 931.21 931.49 931.27 931.43 931.43 931.42 931.41
 23.50 PLEV 931.59 931.58 931.23 931.21 931.21 931.21 931.21 931.21 931.21 931.21 931.21
 23.50 DISCHG 77.36 76.19 75.11 72.97 69.51 62.71 57.00 51.71 46.90 42.53
 23.50 PLEV 931.39 931.38 931.37 931.35 931.31 931.25 931.20 931.15 931.10 931.06

ACRE-FT= 746.28

CFS-IIRS= 9030.54

32.24
30.6188
1.62

TOTAL WATER, IN INCHES ON DRAINAGE AREA=

FNOCMP 1

EXECUTIVE CONTROL CARD
 STARTING TIME 0.00
 ALTERNATE NO. = 1
 OPERATION COMPUT. FROM XSECTN/STRUCT 0/1 TO XSECTN/STRUCT 0/1
 RAIN DEPTH = 0.50 RAIN DURATION = 1.00 RAIN TABLE NO. = 3 SOIL CONDITION = 3

SUBROUTINE RUHOFF STRUCTURE INPUT
 AREA = 0.45
 COMPUTED CURVE NO. = 1
 RUNOFF CURVE = 85.0
 TIME OF CONCENTRATION = 0.41
 PEAK TIMES
 5.26
 10.11
 11.08
 15.88
 20.02
 23.62

1/2 PMF

PEAK DISCHARGES
 10.235
 10.253
 10.253
 11.353
 14.353
 34.672
 32.409

TIME	DISCHG	HYDROGRAPH, TZERO = 2.25	DELTA T = 0.25	AREA = 0.45
2.25	0.00	1.78	5.46	8.19
4.75	9.10	10.235	12.35	82.61
7.25	67.54	91.25	100.35	105.17
9.75	107.03	109.01	111.24	114.00
12.25	206.96	321.54	429.16	537.23
14.75	551.23	560.54	1400.34	526.03
17.25	478.47	425.86	90.30	32.02
19.75	43.59	34.85	32.37	32.36
22.25	32.37	32.37	32.37	32.36
24.75	1.14	0.24	0.00	5.07

TOTAL WATER IN INCHES ON DRAINAGE AREA = 15.3671 CFS-HRS = 4532.29 ACRE-FT = 374.54

SUBROUTINE RESVOR SURFACE ELEVATION 930.00

TIME	DISCHG FLEV	HYDROGRAPH, TZERO = 2.25	DELTA T = 0.25	AREA = 0.45
2.25	0.00	0.01	0.32	0.87
4.75	1.03	1.21	930.01	930.04
7.25	7.02	9.48	1.58	6.20
9.75	49.92	55.33	17.35	930.16
12.25	94.00	116.35	60.94	33.41
14.75	515.17	539.92	197.73	37.93
17.25	545.32	932.61	932.01	931.01
19.75	116.25	105.48	82.79	79.54
22.25	60.42	57.81	49.57	931.44
24.75	30.03	35.10	20.38	420.11

TIME	DISCHG FLEV	HYDROGRAPH, TZERO = 2.25	DELTA T = 0.25	AREA = 0.45
2.25	0.00	0.01	0.32	0.87
4.75	1.03	1.21	930.01	930.04
7.25	7.02	9.48	1.58	6.20
9.75	49.92	55.33	17.35	930.16
12.25	94.00	116.35	60.94	33.41
14.75	515.17	539.92	197.73	37.93
17.25	545.32	932.61	932.01	931.01
19.75	116.25	105.48	82.79	79.54
22.25	60.42	57.81	49.57	931.44
24.75	30.03	35.10	20.38	420.11

TOTAL WATER IN INCHES ON DRAINAGE AREA = 14.7312 CFS-HRS = 4344.73 ACRE-FT = 353.04

ENDCMP 1

EXECUTIVE CONTROL CARD
STARTING TIME= 0.00
ALTERNATE NO.= 1
OPERATION COMPUT.
RAIN DURATION= 1.00
STORM NO.= 1
FROM XSECTN/STRUCT
RAIN TABLE NO.= 4
TO XSECTN/STRUCT
SOIL CONDITION= 3

SUBROUTINE RUNOFF STRUCTURE INPUT
ALPHA= 0.45
COMPUTED CURVE NO.= 1
RUNOFF CURVE= 85.0
TIME OF CONCENTRATION= 0.41

100-YV

TIME	DISCHG	HYDROGRAPH	PEAK DISCHARGES	PEAK ELEVATIONS	DRAINAGE AREA
2.75	0.00	2.35	3.61	4.72	5.70
5.25	6.58	7.32	14.69	28.31	30.23
7.75	35.97	35.43	40.36	41.94	42.66
10.25	85.34	47.24	49.06	46.95	52.05
12.75	143.98	185.59	189.16	207.71	231.69
15.25	190.78	621.55	480.26	247.89	236.43
17.75	185.43	48.59	31.44	25.92	25.86
20.25	26.82	25.96	25.96	25.87	26.83
22.75	25.88	24.33	25.88	17.85	1.03
25.25	0.02	0.00	0.00	0.00	0.45

TOTAL WATER, IN INCHES ON DRAINAGE AREA= 6.9778 CFS-HRS= 2056.01 ACRE-FT= 170.07

SUBROUTINE RESVOR SURFACE ELEVATION= 1
PEAK TIMES
16.1K

TIME	DISCHG	HYDROGRAPH	PEAK DISCHARGES	PEAK ELEVATIONS	DRAINAGE AREA
2.75	0.00	0.01	0.05	0.17	0.45
5.25	0.76	0.88	1.01	1.35	0.53
7.75	4.63	5.29	5.95	7.31	3.38
10.25	13.57	15.20	16.01	20.09	10.14
12.75	37.90	48.65	53.34	81.18	24.39
15.25	196.75	290.51	407.78	440.80	930.77
17.75	233.09	218.17	198.26	142.73	121.79
20.25	79.98	74.92	70.28	62.26	931.69
22.75	46.19	44.60	43.01	39.07	106.45
25.25	30.23	28.65	27.15	24.58	931.52


TOTAL WATER, IN INCHES ON DRAINAGE AREA= 6.4282 CFS-HRS= 1895.31 ACRE-FT= 156.67

ENDCOMP 1

END OF JOB
PATCH JOB

66J

RUSS LAKE SPILLWAY RATING HEG-2



DISCHARGE - CFS

RIDGE LAKE

STEP DAM BY COMPTON USE

44.5' C-2

100' DAM

100' DAM

DAM 100' 552

934

933

932

931

930

ELEV.

931.9

932.2

932.5

933.0

933.5

934.0

Q

0

10

100

450

1200

3340

Using Brd cat water formula
adjusted coef for tree effect

1000

3400

DAM R45

HOSKINS-WESTERN-SONDEREGGER

COMPUTED BY SGJ DATE 10/19/78 SHEET NO. 79 OF 95
CHECKED BY _____ DATE _____ JOB NUMBER 79/3095
PROJECT Mo Dam Insp.

CALCULATIONS FOR

Combined Rating

Riss Lake

	Elev.	Spillway	Dam Embank	Total
	930.0	0		0'
	930.5	10		10'
	931.0	36		36'
	931.5	88		88'
Pl-Dam	931.9	156	0	156'
	932.2	225	40	265'
	932.5	300	130	430'
	933.0	445	450	895'
	933.5	610	1200	1810'
	934.0	790	2340	3130'